

Domestic/Landlord Gas Safety Records

Safety inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulation and the Gas Industry unsafe situation procedure

No detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out

Certificate Reference

21 Damascus Street Certificate No:

| Engineer Details | | | | | | | Installation Details | | | | | Client Details | | | | | | |
|--|----------|--|---------------------------|-------------------------------|------------|-------------|--------------------------|-------------------------|---------------------------------------|--|---|------------------------------------|---|--|--|-----------------------------|--|-----------------------------------|
| Trading Title Address | | CMK Plumbing & Heating 64 Stewartstown Avenue | | | | | Installation Address: | | 21 Damascus Street Belfast | | | Client Address: | | 49 un | University Properties 49 university Street Belfast | | | |
| | | Belfast | | | | | | | | | | | | | | | | |
| | | Postcode: BT119GF | | | | | Postcode: BT | | | 7 1QQ | 1QQ | | | Postcode: BT71FY | | | | |
| Gas Safe No: | | 187825 | | Telephone No: 07711762521 | | | Telephone | | ۷٥: | | | | Telephone No: 07809568137 | | | | | |
| Appliance Details | | | | | | | | Inspection D | | | | | | | | | | |
| | Location | | Appliance Type | Make | Model | Co2 Reading | Co Reading | Flue Type (OF/RS/FL) | Appliance Inspected (Yes/No/NA) | Combustion analysis reading (CO/CO2) ratio | Landlord's Appliances (Yes/No/NA) | Operating pressure (mbar) or | Heat Input (kw) Safety device correct operation (Yes/No/NA) | Ventilation provision satisfactory (Yes/No) | Visual condition of flue and termination satisfactory | Flue performance test | (Pass/Fail/NA) Appliance Serviced (Yes/No/NA) | Appliance safe to use (Yes/No) |
| 1 | Kitchen | | Central Heating Boiler | Vokera | My nut 20e | 5.1 | 41 | RS | 5 YES | 0.0008 | YES | 20.4 mb | | YES | YES | PASS | NO | YES |
| 2 | | | | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | [| Warning No | tice Fixed | |
| Faults/Notes | | | | | | | 1 | Remedial V | vork | | | | | | | warning NO | | |
| 2 | | | | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | |
| Emergency control valve accessible: Yes Gas tightness satisfactory: | | | | | | | YES | Signa | ature Gas ID number: | | | | | | | ſ | | |
| Gas installation pipework visual inspection satisfactory: | | | | | | | | Report | issued by: | | | | | | | L | | |
| Number of appliances tested: 1 Equipotential bonding: | | | | | | Yes | Name | Colm M | | Signed: | gned: < | | | Date: Fri-06-Dec-20 | | ec-2019 | | |
| NEXT INSPECTION DUE ON OR BEFORE: Sun-06-Dec-2020 Installation pass: Yes | | | | | | Yes | Report | Received by: | | - | | | | | L | | | |
| CO alarm fitted and working: YES Smoke alarm fitted and working | | | | | | | NA | Name | Not At | Home | | Signed: | | | | Date: | Fri-06-De | ec-2019 |

The Gas Safety report was created by Gas Checker Software 2016 all rights reserved www.gaschecker.co.uk